

English 1 (3)


SB, Disc rotation, PG 6 XR, PG 8 XR, 2024-11

SYMPTOM/DESCRIPTION

The PG 6 XR and PG 8 XR can potentially be programmed to rotate the disc in the opposite direction (a) compared to the arrows under the drum (b).

This rotation direction can have a negative effect on rotation sensitive tools like T-rex.

To solve the problem, a reprogramming of the VFD parameters to change the rotation is needed.



Note: This reprogramming is only needed if the 4 discs rotate in the wrong direction (a) compared to the arrows (b).

AFFECTED UNITS

- PG 6 XR produced before w.46 2024 with serial numbers up to 202448100026.
- PG 8 XR produced before w.46 2024 with serial numbers up to 202446100045.

CORRECTIVE ACTION

Check the rotation of the discs to see if a reprogramming of the VFD is needed.

Rotation control procedure:

- 1. Remove all tool holders or tools, unless they are secured with screws, before proceeding.
- 2. Set the support wheel in top position so the grinding head is clear of the floor.
- 3. Set the rotation knob in position "0" or slightly to the right on the remote control.
- 4. Start the grinder on the lowest speed.
- 5. Look at the motor fan and stop the grinder. The fan will decrease in speed so you can see if it turns clockwise or counter clockwise.
- 6. If the motor fan/motor is turning clockwise you have the disc rotation correct and do not need any action on the VFD.
- 7. If the motor fan/motor is turning counter clockwise you need to reprogram the VFD according to below procedure.



B3240055A-07

English 2 (3)

PROCEDURE

Reprogramming of the VFD:

- 1. Open the electrical cabinet and power up the grinder. The WFD will light up.
- 2. Use the arrows (up or down) until you see "PAr" in the display.
- 3. Press ENTER.



- 4. Use arrows "UP/DOWN" and "RESET" until you see parameter "b1-14".
- 5. Press ENTER.



- 6. Use the arrows to change the value to "01".
- 7. Press ENTER.
- 8. Press ESC to go back to start menu.
- 9. Start the grinder and repeat the rotation control procedure as explained in the corrective action section, to confirm that the fan rotate clockwise.







B3240055A-07

English 3 (3)

PARTS INFORMATION

No spare parts needed.

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description	
Α	2024-11	00108451	Created	