

SB, Pump and PCB improvements, WT15i, 2023-08

SYMPTOM/DESCRIPTION

Field reports have shown several points of improvements to be done on the WT15i:

1. The spare part pump came without cable connect or cable gland. This has now been corrected.
2. The software on the PCB could cause the WT15i to start by itself. This has been corrected. There is no possibility to update the software in the field, so a new PCB is needed.
3. On/Off buttons stopped working on the Control Panel. This was due to poor quality of cables. This has now been updated to a more robust solution.

AFFECTED UNITS

- New software on PCB implemented on Serial no: 202240100001
- New and more robust On/Off cables implemented on Serial no: 202331100001

PARTS INFORMATION

Part name	Old part no.	New part no.
Pump	577064203	577065202
Control Unit Without BLEM	599599202	599599203
Control Panel	599513704	599513703

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2023-08	00031570	Created