

SB, New Handles, K4000, 2021-09

SYMPTOM/DESCRIPTION

The handle halves on K4000 have been updated in order to make them easier to assemble. The new handle halves are not backward compatible with the older type.

AFFECTED UNITS

K4000 – Implemented on Serial no: **20213200001**.

CORRECTIVE ACTION

The new handle halves are not backward compatible. If one older handle half needs to be replaced, you will have to order two new handle halves and replace them both.

PARTS INFORMATION

Part name	Old part no.	New part no.
HANDLE HALF LEFT	582330204	NLA
HANDLE HALF LEFT	New part	599198801
HANDLE HALF RIGHT	582330304	NLA
HANDLE HALF RIGHT	New part	599198901

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2021-09	00013112	Created