

## SB, New trigger, K970, K1270, 2024-01

### SYMPTOM/DESCRIPTION

Field reports have shown that the trigger on K970 and K1270 can break off. In order to improve this a new trigger has been implemented. Material is added to weak spots of the trigger to make it more robust.

### AFFECTED UNITS

K970 – New Trigger implemented in production on serial no: 20234300794  
K970 CHAIN – New Trigger implemented in production on serial no: 20234300794  
K970 RING – New Trigger implemented in production on serial no: 20234211077  
K1270 – New Trigger implemented in production on serial no: 20234300001

### PARTS INFORMATION

Part Name	Old Part No.	New Part No.
TRIGGER	502471801	502471803
FUEL TANK K970 (STD and RING)	536853901	536853904
FUEL TANK K970 CHAIN	536853902	536853905
FUEL TANK K1270	598806402	598806403

### WARRANTY INFORMATION

The normal warranty policy applies.

### Revision History

Rev.	Date	Order id.	Description
A	2024-01	00038159	Created