

# SB, W-line Pump Connection, W70P, W250P, 2023-09

## SYMPTOM/DESCRIPTION

A new pump connection on W-line requires the cables to be soldered to the contacts.





## AFFECTED UNITS

All units.

## CORRECTIVE ACTION

Make sure to solder the cable in the correct position, the male and female parts are marked with a number.

## PROCEDURE

	RoW	US
Male connection		
Female connection		

**PARTS INFORMATION**

Parts have been added to W70P and W250P IPL.

Motor page:

599835601 Connector Female

599475101 Adapter Plate

591770801 Screw

Tank page:

599835701 Connector Male

529620201 Protective Sleeve

**WARRANTY INFORMATION**

The normal warranty policy applies.

***Revision History***

<b><i>Rev.</i></b>	<b><i>Date</i></b>	<b><i>Order id.</i></b>	<b><i>Description</i></b>
A	2023-09	00032410	Created