

SB, Front sealing pops out, DM400, DM430, 2021-03

SYMPTOM/DESCRIPTION

Quality field reports have shown that on rare occasions, the front sealing on the DM400 and DM430 can be pushed out by water pressure. To remedy this, a washer has been introduced for the three screws on the front water jacket to keep the seal in place.

AFFECTED UNITS

DM400
DM430

CORRECTIVE ACTION

If sealing pops out of position, add a washer for each of the three screws (figure 1) to keep it in place.



Figure 1: Add three washers.

PARTS INFORMATION

Name	Part Number
WASHER	529583501

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2021-03	SB-6492	Created