

SB, Software Update Revision K, DE 110, DE 120, 2023-03

SYMPTOM/DESCRIPTION

New software, Rev K, is available for DE 110 and DE 120 in HSH.

CHANGES IN SOFTWARE

- Main sensor error now also sets the warning led.
- High PCBA temperature now prevents the machine from starting, after starting it just turns on the warning light.
- The fan error only turns on the warning light, does not stop the machine anymore.

Affected Units

| Model | S/N of implementation in production |
|--------|-------------------------------------|
| DE 110 | 970509404H1U2023103000100 |
| DE 120 | 970514805H1U2023116000011 |

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

| Rev. | Date | Order id. | Description |
|------|---------|-----------|-------------|
| A | 2023-03 | 00028639 | Created |