

SB, Motor mix-up, K7000/K6500 Family, 2021-10

SYMPTOM/DESCRIPTION

!!!This service bulletin will be updated!!!


In the progress of updating the motors and cutter arms for a better fit, there has been a mix-up of motors for the K7000 and K6500 family. New motors have been stored together with old motors. The new motors are not possible to install on older machines, without changing the cutter arm. We are working on a solution where the motor is kitted with the respective cutter arm.

AFFECTED UNITS

K7000 Family
K6500 Family

CORRECTIVE ACTION

If you need to change a motor on a K6500 or K7000, please look at the picture below. If you have the new motor, please order a new cutter arm according to "Parts information" below.



PARTS INFORMATION

Part name	Article no.
Cutter arm - Standard	525339402
Cutter arm - RING	581125102
Cutter arm - CHAIN	588576203

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2021-10	00013722	Created