

SB, New robust water nipple, K7000 family, 2023-05

SYMPTOM/DESCRIPTION

Field reports have shown that the water nipple for the motor on PRIME family can break. The nipple has been changed to a more robust water nipple with thicker walls.



Figure 1: Broken water nipple.

AFFECTED UNITS

- K7000 - Implemented on Serial No: 202310XXXXXXXX
- K7000 RING - Implemented on Serial No: 202310XXXXXXXX
- K7000 CHAIN - Implemented on Serial No: 202310XXXXXXXX
- DM700 - Implemented on Serial No: 202310XXXXXXXX

PARTS INFORMATION

Part Name	Old Part No.	New Part No.
Water Nipple	501282902	501282903

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2023-05	00029319	Created