

SB, Rim sprocket holder, K 7000 CHAIN FLUSH, 2025-02

SYMPTOM/DESCRIPTION

Field reports have shown that there are difficulties in installing the rim sprocket on the splineway while the product is lying on its side. To counteract this, a quick field solution has been implemented.

Add one circlip, art. no. 735312000, on the motor shaft. This will prevent the rim sprocket to fall past the splineway.

AFFECTED UNITS

K 7000 CHAIN FLUSH - All

CORRECTIVE ACTION

Add the circlip on the motor shaft as described in the picture. Reinstall everything and don't forget to tighten the screw with the correct torque, refer to SB B3250007A-07.

WARRANTY INFORMATION

The normal warranty policy applies.



PART INFORMATION

Part Name	Part number	Comment
Circlip	735312000	Already existing part

Revision History

Rev.	Date	Order id.	Description
A	2025-02	00134367	Created