

## SB, New CIRCUIT BOARD ASSY, DM220, 2021-11

### SYMPTOM/DESCRIPTION

A number of field reports have shown that the plastic holder for the PCB on DM220 brake easily. We have now implemented a new plastic that is stronger.

### AFFECTED UNITS

DM220 120V – Implemented 2021-09-06 in production.

DM220 230V – Implemented 2021-02-05 in production.

### PARTS INFORMATION

Name	Old Part Number	New Part Number
ELECTRONIC BOX 120V	587674001/501130101	501130103
PRINTED CIRCUIT BOARD 230V	501130102	501130104
CIRCUIT BOARD ASSY 120V	581774901/581774903	581774905
CIRCUIT BOARD ASSY 230V	581774902/581774904	581774906

### WARRANTY INFORMATION

The normal warranty policy applies.

### Revision History

Rev.	Date	Order id.	Description
A	2021-11	00015132	Created