

SB, New Handles, DM220, 2022-06

SYMPTOM/DESCRIPTION

Due to compliance regulations, we have changed the handle halves on the DM220 and removed the lock-on button. This button is replaced by a trigger lock bracket which can be placed inside the handle (see figure 1).

The new handle halves and trigger switch are not backward compatible.

The old handle halves and the trigger will be available as spare parts until they run out of stock.

To use the trigger lock bracket, simply insert it into the handle and rotate the lever to hold the trigger pushed in.

AFFECTED UNITS

DM220 – Implemented in production on serial no: 202227100001

PARTS INFORMATION

To change to a new TRIGGER, the new HANDLE KIT must be ordered.

To change to the new HANDLE KIT a new TRIGGER must be ordered.

To get the function of speed hold on newer machines, the new TRIGGER LOCK BRACKET should be ordered.



Figure 1: New Trigger-Lock Bracket installed.

Part description	Old part no.	New part no.
HANDLE KIT	577244604	NLA
HANDLE KIT	New Part	577244602
TRIGGER	525542104	NLA
TRIGGER	New Part	525542102
TRIGGER LOCK BRACKET	New Part	536334901

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2022-06	00021140	Created