


SB, Actuator play in the axle, Soff-Cut 4000, 2022-04

SYMPTOM/DESCRIPTION

At a certain point when raising or lowering the saw, there is a "dead play". The undesired "dead play" causes the saw to be less smooth. It is irritating for the operator of the saw but does not affect the cutting result or performance during the cut.

A new actuator bracket is introduced and installed in a better way, which eliminates the "dead play".



AFFECTED UNITS

Soff-Cut 4000 from Serial number 1396266001 onwards.

CORRECTIVE ACTION

The new Actuator bracket is product improvement only. Replace only if it breaks!

If the existing Actuator bracket needs to be replaced, order a new Retrofit kit PN 536651701.

PARTS INFORMATION

	Part No	Part description	Qty
Old Actuator bracket	505831002	Actuator	1
New Retrofit kit	536651701	BRACKET KIT	1
Kit content	529858001	BRACKET ACTUATOR	1
Kit content	531196901	BRACKET CARRIAGE	1
Kit content	590960601	SCREW External Hexagon Head Flanged 1/4-20UNC X 1 " Grade 5 ZPB	2

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2022-04	00019501	Created