

## SB, IGNITION SWITCH, FS5000 & FS7000, 2014-10

### SYMPTOM/DESCRIPTION

A new Ignition Switch is introduced on FS5000 and FS7000. This will give customers the option to buy the Switch and Key separate. All keys will from now on have the same marking (CH601).



Figure 1

### AFFECTED UNITS

The new Ignition Switch was introduced in production according to table 1 below.

Product	From S/N
FS5000	001337668001
FS7000	001337670002

Table 1

### PARTS INFORMATION

Spare Part	Old part number	New part number
Switch + Key	586 63 79-01	587 68 10-01
Key	-	587 70 91-01

Table 2

Older style Ignition Switches (586 63 79-01) should be scrapped in local stock.

### WARRANTY INFORMATION

Normal warranty policies applies.