

## SB, Crankcase bearings, K770/K970, 2020-02

### SYMPTOM/DESCRIPTION

Back in late 2018 SKF changed their folded bearings to riveted ones. After extensive testing of these SKF Riveted bearings we have concluded that they are just as good as the folded ones. This service bulletin is only to inform about the change, no action is needed.

### AFFECTED UNITS

K770 all units.

K970 all units.

### PARTS INFORMATION

No change has been made to article numbers.



Figure 1: K770 folded type SKF-bearings (Old)



Figure 2: K970 folded type SKF-bearings (Old)



Figure 3: K770 riveted SKF-bearings (New)



Figure 4: K970 riveted SKF-bearings (New)

### WARRANTY INFORMATION

The normal warranty policy applies.

### Revision History

Rev.	Date	Order id.	Description
A	2020-02	SB-5258	Created