

SB, New Firmware rev. N, PP70, 2024-05

SYMPTOM/DESCRIPTION

A new firmware, rev. N, has been released for PP70. This new firmware includes updates as X-halt and operating hours, see “Release notes” below for complete update description. It is backwards compatible and can be used on all products that previous PP70 firmware revisions have been used on.

Release notes (changes since previous release M):

- Error code 11, “Motor current measurement error”, is now set correctly.
- Fan is running, after an over temperature error situation, until the temperature is below 70 degrees Celsius.
- Added X-Halt with tool LED indication.
- Resistive brake diagnostics is improved.
- Added handling of service time for WS220, WS8, K7000 and DM700.
- PP runtime is now only counting when the connected tool is running.

AFFECTED UNITS

Model	All units after below S/N is produced with the new firmware
PP70	2024 15 5000503

CORRECTIVE ACTION

Update PP70 with Husqvarna Service Hub (HSH).

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2024-05	00045504	Created