

SB, New throttle wire and lever, BG 245, 2024-03

SYMPTOM/DESCRIPTION

Due to the subcontractor having stopped the production of some components, a new throttle wire and lever has been introduced. These are not interchangeable with the old ones. The machines before the listed serial numbers in the *Affected units* table require a retrofit kit to be ordered if a throttle wire or lever is to be replaced.

AFFECTED UNITS

SKU	Model	Serial number
967928801	BG 245 H4 F BC TP	202321100445

CORRECTIVE ACTION

In case an old type throttle cable pos.36 (594252001) or a throttle lever pos.37 (594224101) needs to be replaced with the new type, a retrofit kit should be ordered.


PARTS INFORMATION

548497801 – Retrofit kit for BG 245.

WARRANTY INFORMATION

This bulletin is for information only and doesn't require any action, unless a parts replacement is required.

The normal warranty policy applies.



Revision History

Rev.	Date	Order id.	Description
A	2024-03	00041413	Created
B	2025-06	00180778	Updated part number.