

SB, CYLINDER GASKET, K1270II Family, 2024-06

SYMPTOM/DESCRIPTION


To improve the sealing between cylinder and crankcase, a new paper cylinder gasket with silicone rings has been developed.

AFFECTED UNITS

K1270II All variants – Gasket introduced in production on serial no: **20242203145**

PROCEDURE

When installing the new gasket, make sure the silicon rings on the gasket are facing the crankcase.



PARTS INFORMATION

Part name	Old part no.	New part no.
GASKET CYLINER	587536201	546931301
CRANK CASE KIT	582415004	582415007
ENGINE KIT	582415006	582415008
GASKET KIT	582454801	582454802
CYLINDER ASSY w PISTON	582582303	582582304

Note: Check your local stock! Please use up old parts before ordering new parts.

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2024-06	00056877	Created