

## SB, New arms, RA10, RA10S, 2024-03

### SYMPTOM/DESCRIPTION

New arms have been implemented for RA10 and RA10S. With the implementation of new arms, the spare part offering will also change. Arms and the rail fixture foot will no longer be available as individual spare parts. Wear parts will still be available.

EPC is updated with correct illustrations and part lists.

### AFFECTED UNITS

- K1270 RAIL 16" 20233807632
- K1270 RAIL 14" 20233806539
- RA10 – Will be replaced when current stock is depleted
- RA10S – Complete Spare part replaced.

### PARTS INFORMATION

Part name	Old part no.	New part no.
RA 10	599799203	546376302
RA 10S	599799204	546376502
Arm	544923505	No longer Available
Spacing tube	506227001	No longer Available
Shaft	506227201	No longer Available
Arm	535582901	No longer Available
Label RA10	544887101	No longer Available
Label RA10S	544887102	No longer Available
Spacing tube	506227002	No longer Available
Bar	506236301	506236302

### WARRANTY INFORMATION

The normal warranty policy applies.

#### Revision History

Rev.	Date	Order id.	Description
A	2024-03	00040805	Created