

SB, Special Sealing, K3600, K2500, 2011-01

When running the hydraulic products on to high pressure, and/or flow the shaft sealing can start to leak.

When problems like this occur the original sealing can be replaced by a special sealing.

506 30 11-08



When assembling the sealing it has to pass some sharp corners on the shaft therefore a assembly tool is attached with the sealing together with an instruction.

Please follow the instructions!



