

SB, New PCB, DM400/DM430, 2021-11

SYMPTOM/DESCRIPTION

Field reports has shown that some PCB's on the DM400 and DM430 has broken down at an early stage. In order to improve this, more potting/lacquer material has been added to the PCB. Minor hardware changes has been made as well to improve the situation.

AFFECTED UNITS

DM400 – Implemented on serial number 202136000001

DM430 – Implemented on serial number 202135000001

PARTS INFORMATION

Part Name	Old Article No.	New Article No.
PRINTED CIRCUIT BOARD 230V (with Bluetooth)	598737201	598737205
PRINTED CIRCUIT BOARD 120V (with Bluetooth)	598737202	598737206
PRINTED CIRCUIT BOARD 230V (without Bluetooth)	598737203	598737207
PRINTED CIRCUIT BOARD 120V (without Bluetooth)	598737204	598737208

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2021-11	00015083	Created