

English 1 (2)

SB, New Cover, WS440, WS482, PP440, PP490, PP492, 2024-03

SYMPTOM/DESCRIPTION

New updated position of the rivet on the HARTING contact on Wall Saw, Power Pack and orange cord. This new position will improve the situation with broken covers.





Fig. 1: Old version.

Fig. 2: New version.





English 2 (2)

AFFECTED UNITS

Model	All units after below S/N is sent with the new COVER
WS440	2024 10 08913
WS482	2024 04 03887
PP492	2023 08 05813

PARTS INFORMATION

Description	Old Part No.	New Part No.
COVER	575335401	575335402

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
Α	2024-03	00041565	Created