



English 1 (1)

SB, DM 1, PACE, Display lights, 2024-04

SYMPTOM/DESCRIPTION

The display lights might be lightning up randomly.

AFFECTED UNITS

DM1 PACE in combination with an old software in the batteries.

CORRECTIVE ACTION

Update the battery software according to *Procedure* in this SB.

PROCEDURE

Connect DM 1 PACE to Husqvarna Service Hub (refer to service bulletin B3220007B-07) and update the software.

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2024-04	00041901	Created