

SB, Hardware Changes, K 7000 all variants, 2025-03

SYMPTOM/DESCRIPTION

Due to upcoming legal requirements, new functionality has been added to the PRIME system. As this affects both the power packs and the prime tools, both of them have gone through changes:


PP70

Software revision “N” and forward can handle PRIME tools, like the K7000 which is equipped with new hardware.

K7000

All K7000s from serial No: 202508XXXXXXXXX have the hardware necessary for upcoming legal requirements.

The hardware changes are two current transformers situated on the two of the motor phases, and one additional connector in the display of the K7000. Please refer to highlighted parts in the picture below.



AFFECTED UNITS

PP 70 – Software “N” implemented on serial no: 2024155000503 – See SB B3240036A-07 for reference.

K7000	Changes implemented on PNC: 970744501, S/N: 202508xxxxxxxx
K7000 RING 14”	Changes implemented on PNC: 970756301, S/N: 202508xxxxxxxx
K7000 RING 17”	Changes implemented on PNC: 970756401, S/N: 202508xxxxxxxx
K7000 CHAIN	Changes implemented on PNC: 970756201, S/N: 202508xxxxxxxx
K7000 CHAIN FLUSH	Changes implemented on PNC: 970812901, S/N: 202508xxxxxxxx

PARTS INFORMATION

PART NAME	Old Part No	New Part No
WIRING ASSY – All K7000s	New Part	546538201
DISPLAY K7000 RING 14”	New Part	548726902
DISPLAY K7000 RING 17”	New Part	548726903
DISPLAY K7000 CHAIN	New Part	548726904
DISPLAY K7000 CHAIN FLUSH	New Part	548726904

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2025-03	00145187	Created