

English 1 (3)

# SB, Updated fuel tank, Soff-Cut 4200, Soff-Cut 5000, 2021-06

#### SYMPTOM/DESCRIPTION

The Fuel tank for Soff-cut 4200 & 5000 is updated to avoid leakage. As a result the cover on top of the tank also had to be updated.




Figure 1: Updated fuel tank and cover.

## **AFFECTED UNITS**

Model	PNC	Serial Ra	nge (S/N)
		Start	End
Soff-cut 4200			1202651000
Soff-cut 5000		-	1392651000

The new updated fuel tank and cover is implemented in production from **S/N 1392651001**. All machines produced earlier might potentially be affected.

B3210033A-07

English 2 (3)

#### **CORRECTIVE ACTION**

In case of fuel leakage, replace the old fuel tank (PN 577541601) with the new updated fuel tank kit. For machines before S/N 1392651001 the following retrofit kits should be ordered in case of failure:

Machine model	Replacement kit		Contains	
	Part no.	Description	Part no.	Description
Soff-Cut 4200	534205601	Fuel tank weldment 4200	529501101	New Fuel tank
			577608502	New Cover
Soff-Cut 5000	534205701	Fuel tank weldment 5000	529501101	New Fuel tank
			577608501	New Cover




Figure 2: Updated Fuel tank - P/N 529501101




Figure 3: Updated Cover Soff-Cut 4200 – 577608502



Figure 4: Updated Cover Soff-Cut 5000 - 577608501

#### PARTS INFORMATION

Update sold products during next service if the fuel tank is defective!

Machine model	Description	Old part no.	New part no.	Replacement kit
Soff-Cut 4200	Fuel tank	585507001	529501101	534205601
	Cover	577608502	577608502	(Fuel tank weldment 4200)
Soff-Cut 5000	Fuel tank	505777801	529501101	534205701
	Cover	505664001	577608501	(Fuel tank weldment 5000)



# B3210033A-07

English 3 (3)

## **WARRANTY INFORMATION**

The normal warranty policy applies.

### **Revision History**

			-	
	Rev.	Date	Order id.	Description
	Α	2021-06	00011485	Created