


## SB, Muffler, K970, 2024-05

### SYMPTOM/DESCRIPTION

Field reports have shown that the muffler can come lose on products in the K970 family. As an improvement, longer screws and a sleeve have been introduced for the two top screws. These are the same screws and sleeves that are used to hold down the cylinder on K970.



### AFFECTED UNITS

K 970 – All variants: Solution implemented on Serial No: 202421XXXXXXXX

### PROCEDURE

This solution is backwards compatible. The screws and sleeves can be installed on existing products.

### PARTS INFORMATION

Article Name	Old Article Number	New Article Number
Screw	Already existing article	544218440
Sleeve	Already existing article	578119101

### WARRANTY INFORMATION

The normal warranty policy applies.

#### Revision History

Rev.	Date	Order id.	Description
A	2024-05	00045953	Created