

SB, Blade Guard, K770 DRYCUT/VAC, 2022-06

SYMPTOM/DESCRIPTION

Based on field reports, changes has been implemented to increase the overall quality of the blade guard and the dust shields. Wheels have also been implemented on the blade guard extender.

AFFECTED UNITS

- K770 Drycut, implemented in production on S/N 20211800040.
- K770 VAC, implemented in production on S/N 20211800040.

PARTS INFORMATION

If you have a unit with S/N before specified S/N above, you can order parts according to table below, section “**OLD SYSTEM**”.

If you have a unit with S/N equal to or after specified S/N above, you can order parts according to table below, section “**NEW SYSTEM**”.

Part Name	Old Article no.	New Article no.
OLD SYSTEM, before S/N 20211800040		
BLADE GUARD ASSY	596888204	596888204
BLADE GUARD KIT	596888304	596888304
WHEEL GUARD EXTENDER	593094804	597521702
PLASTIC SHIELD	593081904/593081902	599698301
PLASTIC SHIELD	590488204/590488202	599698401
BUSHING	590488801	Still available
TORSION SPRING	590488504	597129001
NEW SYSTEM, from S/N 20211800040 and after		
BLADE GUARD ASSY	New Part	596888204
BLADE GUARD KIT	New Part	596888304
WHEEL GUARD EXTENDER	New Part	597521701
PLASTIC SHIELD	New part	599698301
PLASTIC SHIELD	New part	599698401
SHAFT	New part	597035401
TORSION SPRING	New Part	597129001
SCREW (2x)	Existing Part	526834502
WHEEL	New Part	598503702




Figure 1: New Movable Blade Guard.




Figure 2: Old Movable blade guard.

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

<i>Rev.</i>	<i>Date</i>	<i>Order id.</i>	<i>Description</i>
<i>A</i>	<i>2022-06</i>	<i>00020601</i>	<i>Created</i>