

SB, CST and HSH, K 1 PACE, 2022-02

SYMPTOM/DESCRIPTION

As Husqvarna Service Hub is not fully ready for K 1 PACE yet, we have implemented basic functionality in Common Service Tool. This Service Bulletin describes how to connect to both CST and HSH.

AFFECTED UNITS

K 1 PACE – All.

PROCEDURE

Common Service Tool

To connect K 1 PACE to Common Service Tool you will need (see figure 1):

- Adapter Cable 529471501 for connecting the battery to the K 1 PACE
- Cable Assy Adapter 529677001
- KVASER Adapter 574035702




Figure 1: Connecting K 1 PACE to Common Service Tool.

Husqvarna Service Hub

To connect K 1 PACE to Husqvarna Service Hub you will need (see figure 2):

- Interface Box 598072801 (RoW) or 598072804 (NA)
- Adapter Cable 529471501




Figure 2: Connecting K 1 PACE to Husqvarna Service Hub.

PARTS INFORMATION

Part no.	Description
529677001	CABLE ASSY ADAPTER
574035702	KVASER CAN ADAPTER
529471501	CABLE ASSY ADAPTER CABLE
598072801	INTERFACE BOX (RoW)
598072804	INTERFACE BOX (NA)

Revision History

Rev.	Date	Order id.	Description
A	2022-02	00017009	Created
B	2025-02	00133780	Part no. changed for "Interface box"