

## SB, Hose comes lose, WT15, 2021-02

### SYMPTOM/DESCRIPTION

Field reports have shown that the hose that connects to the pump in the WT15 can come loose. To remedy this we have glued the hose to the pump.

### AFFECTED UNITS

WT15 – All units.


### CORRECTIVE ACTION

If you have a WT15 where the hose has come lose, please follow below instruction to secure the hose.

1. Clean the surface where the hose should sit.  
Apply glue (Loctite 406) to the pump all around where the hose should sit.



2. Mount the hose on the pump and let it rest for five minutes.
3. Do not use any hose clamp.



## WARRANTY INFORMATION

The normal warranty policy applies.

### Revision History

Rev.	Date	Order id.	Description
A	2021-02	SB-6429	Created
B	2021-11	00014795	New content. Don't use hose clamp.